



Genstor Systems Inc. 1501 Space Park Dr Santa Clara, CA 95054

Tel: (408)980-0121 x 321 Fax: (408)980-0127 Support: support@genstor.com RMA: rma@genstor.com
 For general question, please visit; <http://genstor.com/faq.php> for Frequently Asking Questions

Production Traveler

Order Number: 11xxxxx 1/1 System Serial Number: PA0XXXX

MB: SM X11DPT-PS	x 1	SN: OM177S016766	CASE: SYS-1029TP-DTR	SN: S308385
CPU: XEON 4108	x 4	SN: M7XY846700231	PS: 1 + 1 1000W Red	SN: P1K05CH
		SN: M7XY846700227	FD: N/A	SN:
RAM: 16GB DDR4 2400MHz ECC	x 4	SN:	DVD: N/A	SN:
		SN:	NIC: On Board	x 2 SN:
HD: SSD INTL 240GB	x 4	SN: PHYS7283034P240AGN	NIC:	SN:
		S4500 SN: PHYS7283032D240AGN	VGA: On Board	SN:
		SN: PHYS728300HL240AGN	SCSI:	SN:
		SN: PHYS728301VH240AGN	Other: AOC-MTG-I2TM x2	SN: NA186S006561
		SN:		SN: NA186S006602
		SN:		SN:
		SN:		SN:

Operating System: CentOS 6.9 x86_64 PASS

OS Serial Number: _____

Additional: _____ MB Rev: 1.10 BIOS: 2.0b Updated IPMI: 1.43 Updated

Partitions:

HD:	Mount Point	Size	File System	Raid
/dev/md126p1	/boot	250 MB	EXT4	RAID 1
/dev/md126p2	SWAP	64 GB	SWAP	
/dev/md126p3	/	REST	EXT4	

Additional Information:

-Root Password: genstor	
	Eth0 MAC: AC:1F:6B:41:8A:EC, ED IPMI MAC: 0C:C4:7A:F4:BF:A1 Eth0 MAC: AC:1F:6B:41:8B:3E, 3F IPMI MAC: 0C:C4:7A:F4:E8:79

QC 1 Status: PASS QC 2 Status: PASS QC 3 Status: PASS

(QC1: Evaluating chassis, power supply and computer components before assembly.
 QC2: Evaluating system's status after memtest and CPU_Bum heavy bum-in process.
 QC3: Final check after Operating System is installed and before the shipping.)

Work by: Chris QC by: Chris Date: 7/16/2018